

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20150212-EX16109  
**Report Reference** EX16109-20130513  
**Issue Date** 2015-FEBRUARY-12

**Issued to:** SAUDI FACTORY FOR FIRE EQUIPMENT FZCo  
JEBEL ALI FREE ZONE, SOUTH 1  
P.O. BOX 261281  
DUBAI UNITED ARAB EMIRATES

**This is to certify that  
representative samples of**

INTERNAL-COMBUSTION ENGINES FOR DRIVING  
STATIONARY FIRE PUMPS

Diesel engines for driving stationary fire pumps, Models FC3015-UL,  
FC3020-UL, FC4040-UL, FC4060-UL, FC4085-UL, FC6130-UL,  
FC6150-UL, FC6195-UL, FC6250-UL, FC6300-UL

Have been investigated by UL in accordance with the  
Standard(s) indicated on this Certificate.

**Standard(s) for Safety:** UL 1247 - Diesel Engines for Driving Stationary Fire Pumps  
**Additional Information:** See the UL Online Certifications Directory at  
[www.ul.com/database](http://www.ul.com/database) for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's  
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please  
contact a local UL Customer Service Representative at [www.ul.com/contactus](http://www.ul.com/contactus)

